

03512209 in 030001

BEST AVAILABLE COPY




FIG. 2A




FIG. 2B





FIG. 2C



PRIOR
ART

TOP SECRET 60287660




Fig. 3
PROK ART




FIG. 4
PRIOR ART




Figure 5

四庫全書

* Indicates frequency assignment from the same band but not necessarily identical frequency channel




FIGURE 6




Figure 7

FOTR80-6048T660




FIGURE 8a

TO TOBOBO "60X8T650




FIGURE 8b




FIGURE 8C




FIGURE 9

FOT0000-60287660




FIGURE 10




FIGURE || a




FIGURE 11b

FOTO 080 "6028T660




FIGURE 12




FIG. 13




FIG. 14




Fig. 15




FIG. 16




FIGURE 17a
Cluster Size of 4 with 12 RF Channels

TOP SECRET//SI//COMINT




FIGURE 17b
Cluster Size of 8 with 24 RF Channels

09918709 • 090104




FIGURE 18.a




FIGURE 18.b




FIGURE 19




FIGURE 20




FIGURE 21





FIGURE 22



2350 FIGURE 23




FIGURE 24

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.